

Exception TL200 Wood Stove

1.	1-10-08074	Damper linkage weldment
2.	1-10-08075	Damper pivot arm weldment
3.	1-10-08127	Top lift arm weldment
4.	2-00-05204	Left side shield
5.	3-40-05228	Wooden knob
6.	3-40-05171	Ceramic fiber afterburner
7.	1-10-08058	Left side plate assy.
8.	2-00-07071-1	Left glass retainer clip
9.	2-00-07071-2	Right glass retainer clip
10.	3-40-05180	Afterburner glass
11.	4-31-08078	Brass plated hinge (2 per)
12.	2-00-04174	Hinge plate (4 per) (not shown)
13.	1-10-08076	Front top weldment
14.	2-00-05205	Right side shield
15.	1-10-08073	Ash door hinge weldment
16.	2-00-05169	Airwash extension
17.	1-10-05146	Airslide weldment
18.	3-50-05229	Latch bushing
19.	1-10-08077	Damper weldment
20.	1-10-08057	Damper frame assy.
21.	1-10-08059	Right side plate assy.
22.	1-10-08200	Afterburner hood weldment
23.	1-10-08111	Ramp assy.
24.	3-40-05174	IR glass
25.	3-44-11862	1/4" OD rope 60" (not shown)
26.	3-44-53500	1/2" door rope (66"per) (not shown)
27.	4-00-05165	Cast door-machined
28.	2-00-05202	Glass retainer clips (4 per)
29.	3-00-05165-4	Gold plated cast door (optional, same as 27)
30.	2-00-05222	Andiron (2 per)
31.	2-00-05147	Grates (2 per)
32.	1-10-08133	Grate support weldment
33.	3-40-900450125	Standard brick (4 per)
34.	4-40-08113	Angle cut brick (2 per)
35.	4-40-08115	Side cut brick (2 per)
36.	4-31-08055	Paw bolt
37.	3-40-00121	Brass elbow
38.	3-40-00122	Wooden handle
39.	1-10-08158	Ash door assy.
40.	2-00-05191	Ash door latch
41.	2-00-05226	Damper Clip (2 per)
42.	1-10-05148	Ash pan assembly (not shown)
43.	3-40-05185	Brick insulation (2 per) (not shown)
44.	2-00-05223	Andiron extension (2 per) (not shown)