

Jøtul C 550 CB Replacement Blowers

The new replacement blowers have larger impeller housings. It is necessary to remove the left and right bottom surround trim and the bottom trim bracket. Loosen the two M6 nuts (10mm wrench or socket) and slide the trim and the trim bracket forward.

Loosen M6 Nut

Loosen M6 Nut

