

VANTAGE Winston Masonry Replacement Bricks

MODELS: VGM50HR, VGM50HI

Part Number	Description
50" Herringbone Left Side	
122456-36	Box, Left Side 50" Red
112140-01	Full Red Brick - 6
F064R	Red Brick - 4
F068R	Red Brick - 4
F072R	Red Brick - 2
F074R	Red Brick - 2
F120R	Red Brick - 4
F163R	Red Brick - 1
F169R	Red Brick - 1
F175R	Red Brick - 1
F176R	Red Brick - 1
F177R	Red Brick - 1
F182R	Red Brick - 1
122456-40	Box, Left Side 50" Ivory
112140-05	Full Ivory Brick - 6
F064W	Ivory Brick - 4
F068W	Ivory Brick - 4
F072W	Ivory Brick - 2
F074W	Ivory Brick - 2
F120W	Ivory Brick - 4
F163W	Ivory Brick - 1
F169W	Ivory Brick - 1
F175W	Ivory Brick - 1
F176W	Ivory Brick - 1
F177W	Ivory Brick - 1
F182W	Ivory Brick - 1
50" Herringbone Right Side	
122457-36	Box, Right Side 50" Red
112140-01	Full Red Brick - 9
F068R	Red Brick - 2
F072R	Red Brick - 1
F074R	Red Brick - 2
F083R	Red Brick - 3
F084R	Red Brick - 4
F085R	Red Brick - 1
F093R	Red Brick - 1
F166R	Red Brick - 1
F167R	Red Brick - 1
F172R	Red Brick - 1
F173R	Red Brick - 1
F183R	Red Brick - 1
122457-40	Box, Right Side 50" Ivory
112140-05	Full Ivory Brick - 9
F068W	Ivory Brick - 2
F072W	Ivory Brick - 1
F074W	Ivory Brick - 2
F083W	Ivory Brick - 3
F084W	Ivory Brick - 4
F085W	Ivory Brick - 1
F093W	Ivory Brick - 1
F166W	Ivory Brick - 1
F167W	Ivory Brick - 1
F172W	Ivory Brick - 1
F173W	Ivory Brick - 1
F183W	Ivory Brick - 1

Part No.	Description
50" Herringbone Rear	
122458-36	Box, Rear 50" Red
112140-01	Full Red Brick - 9
F063R	Red Brick - 3
F065R	Red Brick - 3
F068R	Red Brick - 2
F072R	Red Brick - 2
F074R	Red Brick - 2
F082R	Red Brick - 1
F089R	Red Brick - 1
F161R	Red Brick - 2
F168R	Red Brick - 2
F170R	Red Brick - 1
F178R	Red Brick - 1
122458-40	Box, Rear 50" Ivory
112140-05	Full Ivory Brick - 9
F063W	Ivory Brick - 3
F065W	Ivory Brick - 3
F068W	Ivory Brick - 2
F072W	Ivory Brick - 2
F074W	Ivory Brick - 2
F082W	Ivory Brick - 1
F089W	Ivory Brick - 1
F161W	Ivory Brick - 2
F168W	Ivory Brick - 2
F170W	Ivory Brick - 1
F178W	Ivory Brick - 1